

## LIST OF HOTKEY COMMANDS

1/01/01	F atia
Key(s)	Function
А	Center view
ALT	Shows the string menu hotkeys
ALT+C	Clone selected element
В	Machining
CRTL+ 0-9	Change View
CRTL + I	Invert selection
CRTL + O	Open file
CRTL+ P	Print
CRTL+ S	Save file
CTRL+ N	New file
Del	Delete selected element
E	Activate select and move mode / go to items tab
F	Hide fronts
G	Only show selected
Н	Hide selected
J	Show everything
L	Link Selection
М	Materials tab
Click+ALT	Substractive selection
Click+CRTL	Additive selection
Click+Shift	Selection frame
0	Explosion view
R	Ruler/measuring tape
S	Show seperators
Т	Toggle transparency
V	Volume selection mode
W	Panels list
X	Export tuning